

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/05/2019

Submitted Date:

11/05/2019

Document Number:

694900736

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: _____ On-Site Inspection
 335069 _____ Ramsey, Scott _____ 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: _____ 96850 _____
 Name of Operator: TEP ROCKY MOUNTAIN LLC _____
 Address: PO BOX 370 _____
 City: _____ PARACHUTE _____ State: _____ CO _____ Zip: _____ 81635 _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 _____ Number of Comments

0 _____ Number of Corrective Actions

Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262717	WELL	PR	07/12/2002	GW	045-08049	CLOUGH RMV 160-22	PR
284637	WELL	PR	05/09/2006	GW	045-12248	CLOUGH RMV 225-22	PR
284639	WELL	PR	05/09/2006	GW	045-12247	CLOUGH RWF 423-22	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 11/5/19 at approximately 10:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 423-22, at Location # 335069 in Garfield County, Colorado.
 While there, I observed normal production operations.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good:

Emergency Contact Number:	
Comment:	911
Corrective Action:	
	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:				corrective date
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:		Date:		
Type: Deadman # & Marked	# 3			
Comment:				
Corrective Action:		Date:		

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 262717 Type: WELL API Number: 045-08049 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 284637 Type: WELL API Number: 045-12248 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 284639 Type: WELL API Number: 045-12247 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Ditches				
Gravel						
Compaction		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900743	694900736	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981479