



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	At time of inspection Well head sign is adequate but starting to peal off metel sign will need to be replaced in the near future.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

<b>Good Housekeeping:</b>			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment: PU, Horses head and flow lines.		
Corrective Action:	Comply with Rule 603.f	Date:	08/31/2019

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Steel rod		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	Electric panel		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:		
Corrective Action:	Date:	

**Inspected Facilities**

Facility ID: 240786 Type: WELL API Number: 123-08574 Status: TA Insp. Status: TA

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: TA Form 05 A submitted on 8/13/2019 Doc. # 402141465 approved.  
Form 21 (MIT) submitted on 9/4/2019 Doc. # 402165748 approved

Corrective Action:

Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Tuesday 11/5/2019 at approximately 1530 hrs. I, Inspector Robbie Revas, conducted an on-site inspection at a KP Kauffman site, Jillson #3, at API# 05-123-08356 in Weld County Colorado.                      While there, I observed a temporary abandoned well site. This is a follow up inspection per Doc. # 693500943                      During this inspection the following possible compliance issues appear to have been addressed:                      Weeds: Rule 603 f weeds appear to have been cut around location.                      Reporting: Rule 206 Form 05 A was submitted on 8/13/2019 Doc. # 402141465 and is approved.                      MIT: Rule 319 b form 21 was submitted on 9/4/2019 Doc. # 402165748 and is approved.                      At time of inspection I observed PU and flow lines have been disconnected from WH they are considered unused equipment. Form 4 TA                      Status was submitted to the COGCC 8-6-15 Doc#400880968. See attached location photos.                      Weather: clear location is wet.                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	11/05/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300501	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981588</a>