

MARALEX RESOURCES, INC.– 53255
API# 05-077-08216 LIPAN WASH UNIT #3-15-2-2
Inspection Date : 11/4/2019



Overview of location looking. SE anchor looking N.



Wellhead with fence.

MARALEX RESOURCES, INC.– 53255
API# 05-077-08216 LIPAN WASH UNIT #3-15-2-2
Inspection Date : 11/4/2019



Audible leak at Surface casing / Production casing seal.



Separator and Meter housing looking SW

MARALEX RESOURCES, INC.– 53255
API# 05-077-08216 LIPAN WASH UNIT #3-15-2-2
Inspection Date : 11/4/2019



Separator with sign. Sign not visible from location entrance.



**Open ended burner flue on separator
with no bird/wildlife screen.**

MARALEX RESOURCES, INC.– 53255
API# 05-077-08216 LIPAN WASH UNIT #3-15-2-2
Inspection Date : 11/4/2019



Meter housing with sales line riser.



**Produced water tank and blowdown pit
with fence and netting.**

MARALEX RESOURCES, INC.– 53255
API# 05-077-08216 LIPAN WASH UNIT #3-15-2-2
Inspection Date : 11/4/2019



Produce water tank with fade and peeling labels.



**Meter with Out of Service label
Dated 3/19/13**