

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/04/2019

Submitted Date:

11/06/2019

Document Number:

693801222

FIELD INSPECTION FORM

Loc ID 312441 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:

- 11 Number of Comments
- 5 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector
,		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
Ried, Jordan	970-563-4000	maralextechjr@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221613	WELL	SI	09/01/2011	GW	077-08215	LIPAN WASH UNIT 1-14-2-2	SI

General Comment:

COGCC staff performed a followup field inspection on 8/28/2019. Followup to inspection doc#680404075 on 12/10/2018. Issues were found requiring corrective action. CA(s) from previous inspection not completed. See inspection text and photos for details. Any Corrective Actions from previous inspections that have not been addressed are still applicable.

Location			
Lease Road:			
Type	Access		
comment:	BLM		
Corrective ActionL			Date:
Type	Main		
comment:	BLM		
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign at meter housing.		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 12/06/2019
Emergency Contact Number:			
Comment:	No emergency contact information		
Corrective Action:	Install sign to comply with Rule 210.e.		Date: 12/06/2019
Good Housekeeping:			
Type	TRASH		
Comment:	Trash and gravel dumped off NW corner of location.		
Corrective Action:	Comply with Rule 603.f .		Date: 11/15/2019
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	Wildlife fence and netting		
Corrective Action:			Date:
Equipment:			
			corrective date
Type: Deadman # & Marked	# 3		
Comment:	Guy line anchors not marked		
Corrective Action:	Install proper guy line markers per Rule 1003.a		Date: 11/26/2019
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:

Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 221613 Type: WELL API Number: 077-08215 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Well shut in 11/2011.
No current MIT on record or delinquent as required by Rule 326

Corrective Action: Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.
CA from previous inspection not completed. CA date remains the same as previous inspection.

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801230	Inspection photos 11/4/2019	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981947