

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/04/2019

Submitted Date:

11/06/2019

Document Number:

693801223

**FIELD INSPECTION FORM**Loc ID 312553 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 53255

Name of Operator: MARALEX RESOURCES INC

Address: P O BOX 338

City: IGNACIO State: CO Zip: 81137

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ried, Jordan	970-563-4000	maralextechjr@gmail.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	
,		dnr_cogccengineering@state.co.us	
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	Field Inspector

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221899	WELL	SI	03/01/2016	GW	077-08501	LIPAN WASH 10-16-2-2	SI

**General Comment:**

COGCC staff performed a routine field inspection on 11/4/2019.  
Issues were found requiring corrective action. See inspection text and photos for details.

Location				
<b>Lease Road:</b>				
Type	Main			
comment:	BLM			
Corrective Action	L			Date:
Type	Access			
comment:	BLM			
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:	Sign and operator information faded and not legible			
Corrective Action:	Install sign to comply with Rule 210.e.			Date: 12/06/2019
Emergency Contact Number:				
Comment:	No emergency contact information			
Corrective Action:	Install sign to comply with Rule 210.b.			Date: 12/06/2019
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Door and panels blown off of meter housing			
Corrective Action:	Comply with Rule 603.f .			Date: 11/15/2019
Overall Good: <input checked="" type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <input type="text"/>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	WELLHEAD			
Comment:	Pipe fence			
Corrective Action:				Date:
<b>Equipment:</b>				
			corrective date	
Type: Deadman # & Marked	# 3			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	STEEL AST		39.242099,-108.712667	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 221899 Type: WELL API Number: 077-08501 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment:

Well shut in 3/2016.  
Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action:

Produce well after performing successful mechanical integrity test per Rule 326 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.

Date: 12/06/2019

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 39.242099Long: -108.712667Reference Point: SEOther: Length: 15Width: 15**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**Fencing Type: Netting/Fence comFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**Netting Type: Fence/Net ComboNetting Condition: GoodComment: Corrective Action: Date: 

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment: Corrective Action: Date: **Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801231	Inspection photos 11/4/2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981948">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4981948</a>