

Inspection Photos
Location Name: Espinosa #1
API: 05-067-05781



Logos Operating LLC Espinosa #1 observed to be temporarily abandoned during this inspection.



Netting on produced water vessel has fallen into tank.

Inspection Photos
Location Name: Espinosa #1
API: 05-067-05781



Secondary containment for produced water vessel has animal burrows in it and appears to be insufficient capacity.



Espinosa #1 well head.