

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2019

Submitted Date:

11/06/2019

Document Number:

687905786

**FIELD INSPECTION FORM**

Loc ID 313533 Inspector Name: Stewart, Joseph On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 46685  
Name of Operator: KINDER MORGAN CO2 CO LP  
Address: 1001 LOUISIANA ST SUITE 1000  
City: HOUSTON State: TX Zip: 77002

**Findings:**

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name      | Phone          | Email                                 | Comment                         |
|-------------------|----------------|---------------------------------------|---------------------------------|
| Labowskie, Steve  |                | steve.labowskie@state.co.us           | <a href="#">COGCC</a>           |
| Hannigan, Michael | (970) 882-5532 | CO2Source_Regulatory@kindermorgan.com | <a href="#">All Inspections</a> |
| Pesicka, Conor    |                | conor.pesicka@state.co.us             |                                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name                  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------------|-------------|
| 224372      | WELL | SI     | 04/01/2018  | GW         | 083-06437 | MCELMO DOME UNIT 31-37-17 MC-4 | SI          |

**General Comment:**

[Site inspection and equipment inventory with photos at the end of this report.](#)

| Location   |  |        |                  |
|--|--|--------|------------------|
| <b>Lease Road:</b>                                     |  |        |                  |
| Type   | Access   |        |                  |
| comment:   | Gravel access road.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Signs/Marker:</b>                                   |  |        |                  |
| Type   | WELLHEAD   |        |                  |
| Comment:   | Sign posted at entrance to location.   |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Emergency Contact Number:</b>                       |  |        |                  |
| Comment:   | Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo. |        |                  |
| Corrective Action:                                     | Update sign to include local emergency contact or "911" per Rule 210.  |        | Date: 12/06/2019 |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Spills:</b>   |  |        |                  |
| Type   | Area   | Volume |                  |
| In Containment: No                                     |  |        |                  |
| Comment:   |  |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                  |
| <b>Equipment:</b>                                      |  |        | corrective date  |
| Type: Flow Line  | # 1  |        |                  |
| Comment:   | 1-6" SS flowline from wellhead to offsite gathering system.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Ancillary equipment                              | # 1  |        |                  |
| Comment:   | Power disconnect panel.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Ancillary equipment                              | # 1  |        |                  |
| Comment:   | Wellhead with block valve assembly installed.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Deadman # & Marked                               | # 4  |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Venting:</b>  |  |        |                  |
| Yes/No   | NO   |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Flaring:</b>  |  |        |                  |
| Type   |  |        |                  |
| Comment:   |  |        |                  |

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 224372 Type: WELL API Number: 083-06437 Status: SI Insp. Status: SI

**Producing Well**

Comment: [Producing.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs  | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|-------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel            | Pass            |                         |                       |               |                          |         |
| Compaction        | Pass            | Culverts                | Pass                  |               |                          |         |
| Gradient Terraces | Pass            | Gravel                  | Pass                  |               |                          |         |
| Ditches           | Pass            | Ditches                 | Pass                  |               |                          |         |
| Berms             | Pass            | Compaction              | Pass                  |               |                          |         |

Comment: [Stormwater BMP's appear to be functioning at time of inspection.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                                 | URL   |
|--------------|---|---|
| 687905787    | Sign missing emergency contact information. | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982494">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982494</a> |
| 687905788    | Overview photo looking North.               | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982495">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982495</a> |