

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2019

Submitted Date:

11/06/2019

Document Number:

687905792**FIELD INSPECTION FORM**Loc ID 313489 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46685Name of Operator: KINDER MORGAN CO2 CO LPAddress: 1001 LOUISIANA ST SUITE 1000City: HOUSTON State: TX Zip: 77002**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**10 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224222	WELL	PR	03/06/2018	GW	083-06287	SAND CANYON (DEEP) UNIT 2-36-18 6	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report.

Location

Lease Road:			
Type	Access		
comment:	Gravel road access.		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location has been damaged by bullet holes.		
Corrective Action:	Replace sign per Rule 210.	Date:	12/06/2019

Emergency Contact Number:

Comment: Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo.

Corrective Action: Update sign to include local emergency contact or "911" per Rule 210.

Date: 12/06/2019

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Flow Line	# 1		
Comment:	1-6" SS flowline from wellhead to offsite gathering system.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	224222	Type:	WELL	API Number:	083-06287	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
				Material Handling And Spill Prevention	Pass	Spill prevention for 1000Gal glycol tank.
Gradient Terraces	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905793	Damaged sign missing emergency contact information	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982498
687905794	Overview photo looking West.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982499