

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101490

FIELD INSPECTION FORMLoc ID 413974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
432063	WELL	PR	09/01/2013	OW	123-36937	North Platte U-Y-34HNB	SI

General Comment:

This is a WELL inspection.
 Well(s): 1 ; Shut-In | SI.
 Battery: Shut-down | Inactive
 Centralized Battery serves 2 Location IDs (429920, 413974).
 (Well(s): 2 ; Shut-In | SI).
 (2: Other wells associated w/ Location ID #413974 are connected to another Battery/Facility.)

Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920
 for Battery / Facility, Equipment info.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type				
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign with company & well name NOT posted at wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.			
Corrective Action:	* Post sign with company & well name at wellsite. Comply w/ Rule 210.b. See photo #1.			Date: 12/30/2019
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No _____				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Equipment:				
Type:	#			corrective date
Comment:	Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Type: Bradenhead	# 1			

Comment:		Appears plumbed to surface.		Date:	
Corrective Action:				Date:	
Type: Horizontal Heated Separator	# 0				
Comment:				Date:	
Corrective Action:				Date:	
Type: Ancillary equipment	# 0				
Comment:				Date:	
Corrective Action:				Date:	
Type: Pig Station	# 0				
Comment:				Date:	
Corrective Action:				Date:	
Type: Emission Control Device	# 0				
Comment:				Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:				Date:	
Corrective Action:				Date:	
Type: Gas Meter Run	# 0				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.363310,-104.414227
Comment:		Centralized Battery serves 2 Location IDs (429920, 413974). Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.			
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	0				,
Comment:					
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	0				,
Comment:					
Corrective Action:				Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 432063 Type: WELL API Number: 123-36937 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Shut-In | SI. Observed production valves closed.
COGCC records indicate last production: 08/2019.

Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 10/30/2019 at approximately 16:13 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC Location Name: North Platte /41-34 Pad Location ID: 413974 Well Name: North Platte U-Y-34HNB API: 05-123-36937 Location County: Weld County, Colorado Weather: Clear w/ prior snow cover</p> <p>While there, I observed: Well(s): 1 ; Shut-In SI. Battery: Shut-down Inactive</p> <p>Centralized Battery serves 2 Location IDs (429920, 413974). (Well(s): 2 ; Shut-In SI). (2: Other wells associated w/ Location ID #413974 are connected to another Battery/Facility.)</p> <p>Refer to Field Inspection Report Doc. #696101488 and/or Location ID #429920 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed: 1.) Sign with company & well name NOT posted at wellsite. Refer to Rule 210.b. (60 Days). * Post sign with company & well name at wellsite. Comply w/ Rule 210.b. Corrective Action date: 12/30/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p>	evinsb	10/31/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402227851	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977808
696101491	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977807