

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2019

Submitted Date:

10/31/2019

Document Number:

696101494

**FIELD INSPECTION FORM**Loc ID 413974 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email                            | Comment         |
|--------------|-------|----------------------------------|-----------------|
| ,            |       | EHSRC@bonanzacrk.com             | All Inspections |
| ,            |       | dnr_cogccengineering@state.co.us |                 |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name      | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 412522      | WELL | TA     | 04/01/2019  | OW         | 123-30518 | NORTH PLATTE 41-34 | TA          |
| 429081      | WELL | SI     | 04/01/2019  | OW         | 123-35676 | North Platte 42-34 | TA          |

**General Comment:**

This is a WELL & BATTERY inspection.  
Well(s): 2 ; Temporarily Abandoned | TA.  
Battery: Shut-down | Inactive

Centralized Battery serves 2 Location IDs (413457, 413974).  
(Well(s): 4 ; 2: Shut-In | SI ; 2:Temporarily Abandoned | TA).  
(1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)

Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457  
for Battery / Facility, Equipment info.

| Location   |  |        |                  |
|--|--|--------|------------------|
| <b>Lease Road:</b>                                     |  |        |                  |
| Type   | Access   |        |                  |
| comment:   | Adequate   |        |                  |
| Corrective Action                                      | L  |        | Date:            |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Signs/Marker:</b>                                   |  |        |                  |
| Type   |  |        |                  |
| Comment:   | Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type   | WELLHEAD   |        |                  |
| Comment:   | Sign with company & well name NOT posted at North Platte 42-34 wellsite. Refer to Rule 210.b. (60 Days).<br>* Post sign with company & well name at North Platte 42-34 wellsite. Comply w/ Rule 210.b.<br>Corrective Action date: 12/30/2019.<br>See photo #2. |        |                  |
| Corrective Action:                                     | * Post sign with company & well name at North Platte 42-34 wellsite. Comply w/ Rule 210.b.<br>See photo #2.  |        | Date: 12/30/2019 |
| Emergency Contact Number:                              |  |        |                  |
| Comment:   |  |        |                  |
| Corrective Action:                                     |  |        | Date: _____      |
| Overall Good: <input type="checkbox"/>                 |  |        |                  |
| <b>Spills:</b>   |  |        |                  |
| Type   | Area   | Volume |                  |
| In Containment: No                                     |  |        |                  |
| Comment:   |  |        |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                  |
| <b>Fencing/:</b>                                       |  |        |                  |
| Type   |  |        |                  |
| Comment:   | Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type   | WELLHEAD   |        |                  |
| Comment:   | 2 - Wellsites: Iron panel  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| <b>Equipment:</b>                                      |  |        |                  |
| Type: Other  | # 2  |        | corrective date  |
| Comment:   | 2 - Wellsites: w/ Master & casing valves.  |        |                  |
| Corrective Action:                                     |  |        | Date:            |
| Type: Bradenhead                                       | # 2  |        |                  |
| Comment:   | 2 - Wellsites: Appears plumbed to surface.   |        |                  |

|                    |   |       |  |
|--------------------|---|-------|--|
| Corrective Action: |   | Date: |  |
| Type:              | #   |       |  |
| Comment:           | Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info. |       |  |
| Corrective Action: |   | Date: |  |

**Tanks and Berms:**

|                    |   |          |                     |         |                       |
|--------------------|---|----------|---------------------|---------|-----------------------|
| Contents           | #   | Capacity | Type                | Tank ID | SE GPS                |
|                    |   |          | CENTRALIZED BATTERY |         | 40.363892,-104.413841 |
| Comment:           | Centralized Battery serves 2 Location IDs (413457, 413974). Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info. |          |                     |         |                       |
| Corrective Action: |   |          |                     | Date:   |                       |

**Paint**

|                  |  |
|------------------|--|
| Condition        |  |
| Other (Content)  |  |
| Other (Capacity) |  |
| Other (Type)     |  |

**Berms**

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|                    |          |                     |                     |             |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     | Date:               |             |

**Venting:**

|                    |    |       |
|--------------------|----|-------|
| Yes/No             | NO |       |
| Comment:           |    |       |
| Corrective Action: |    | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**Facility ID: 412522 Type: WELL API Number: 123-30518 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
COGCC records indicate last production: 08/2018.  
Form 5A doc #401901355 indicates TA date: 08/01/2018. Approval PENDING.

Corrective Action:  Date: Facility ID: 429081 Type: WELL API Number: 123-35676 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: EQUIPMENT PRESENT/DISCONNECTED

Comment: Temporarily Abandoned | TA. Observed well disconnected from flowline.  
COGCC records indicate last production: 03/2019.

Corrective Action:  Date:

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 10/30/2019 at approximately 16:19 hrs. I, Bret Evins, conducted an on-site inspection at:<br/> Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC<br/> Location Name: North Platte /41-34 Pad<br/> Location ID: 413974<br/> Well Names: North Platte 41-34, North Platte 42-34<br/> API: 05-123-30518, 05-123-35676<br/> Location County: Weld County, Colorado<br/> Weather: Clear w/ prior snow cover</p> <p>While there, I observed:<br/> Well(s): 2 ; Temporarily Abandoned   TA.<br/> Battery: Shut-down   Inactive</p> <p>Centralized Battery serves 2 Location IDs (413457, 413974).<br/> (Well(s): 4 ; 2: Shut-In   SI ; 2:Temporarily Abandoned   TA).<br/> (1: Other well associated w/ Location ID #413974 is connected to another Battery/Facility.)</p> <p>Refer to Field Inspection Report Doc. #696101492 and/or Location ID #413457 for Battery / Facility, Equipment info.</p> <p>During this inspection, the following possible compliance issues were observed:<br/> 1.) Sign with company &amp; well name NOT posted at North Platte 42-34 wellsite.<br/> Refer to Rule 210.b. (60 Days).<br/> * Post sign with company &amp; well name at North Platte 42-34 wellsite.<br/> Comply w/ Rule 210.b.<br/> Corrective Action date: 12/30/2019.<br/> See photo #2.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 10/31/2019 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402228203    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977938">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977938</a> |
| 696101495    | Site photos          | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977929">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4977929</a> |