

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/07/2019

Submitted Date:

11/07/2019

Document Number:

693200444

FIELD INSPECTION FORM

Loc ID 335604 Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Heil, John		john.heil@state.co.us	
, Inspections		COGCCInspectionReports@terraep.com	Field Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
263949	WELL	PR	12/13/2002	GW	045-08161	FEDERAL RWF 323-18	EG
263950	WELL	PR	05/29/2002	GW	045-08162	FEDERAL RMV 169-18	EG
283001	WELL	PR	02/02/2006	GW	045-11892	FEDERAL RMF 412-18	EG
283002	WELL	PR	02/02/2006	GW	045-11891	FEDERAL RWF 512-18	EG
283003	WELL	PR	10/11/2006	GW	045-11890	FEDERAL RWF 422-18	EG
283004	WELL	PR	10/11/2006	GW	045-11889	FEDERAL RWF 522-18	EG
291084	WELL	PR	06/19/2007	GW	045-14295	FEDERAL RWF 23-18	EG
291085	WELL	PR	06/19/2007	GW	045-14294	FEDERAL RWF 13-18	EG

General Comment:

Engineering Integrity Inspection performed on November 7, 2019. In response to initial form 19 spill report Document #40218609

Inspected Facilities

Facility ID: 263949 Type: WELL API Number: 045-08161 Status: PR Insp. Status: EG

Flowline

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel
 Variance: No Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Internal Corrosion Spills: Yes Repairs Made: Yes
 Coatings: No H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: 2" dump line low pressure running from separator to tank battery, hole was is a straight run and caused by internal corrosion.

Corrective Action: Date:

Facility ID: 263950 Type: WELL API Number: 045-08162 Status: PR Insp. Status: EG

Facility ID: 283001 Type: WELL API Number: 045-11892 Status: PR Insp. Status: EG

Facility ID: 283002 Type: WELL API Number: 045-11891 Status: PR Insp. Status: EG

Facility ID: 283003 Type: WELL API Number: 045-11890 Status: PR Insp. Status: EG

Facility ID: 283004 Type: WELL API Number: 045-11889 Status: PR Insp. Status: EG

Facility ID: 291084 Type: WELL API Number: 045-14295 Status: PR Insp. Status: EG

Facility ID: 291085 Type: WELL API Number: 045-14294 Status: PR Insp. Status: EG

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200445	TEP 1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983698
693200446	TEP 2	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983699