

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/23/2019

Submitted Date:

11/01/2019

Document Number:

689803230

**FIELD INSPECTION FORM**

Loc ID 313120 Inspector Name: Waldron, Emily On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10133  
 Name of Operator: HILCORP ENERGY COMPANY  
 Address: P O BOX 61229  
 City: HOUSTON State: TX Zip: 77208

**Findings:**

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone          | Email                | Comment                         |
|---------------|----------------|----------------------|---------------------------------|
| Fillpot, Greg | (307) 299-3829 | gfillpot@hilcorp.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 258684      | WELL | PR     | 12/08/2000  | GW         | 081-07003 | DYER C 3      | PR          |

**General Comment:**

[Routine FIU inspection.](#)

**Location**

Overall Good:

**Signs/Marker:**

|                    |   |       |            |
|--------------------|---|-------|------------|
| Type               | TANK LABELS/PLACARDS                                |       |            |
| Comment:           | Tank labeled as both condensate and produced water. |       |            |
| Corrective Action: | Install sign to comply with Rule 210.d.             | Date: | 01/01/2020 |
| Type               | WELLHEAD  |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |
| Type               | BATTERY   |       |            |
| Comment:           |   |       |            |
| Corrective Action: |   | Date: |            |

Emergency Contact Number:

|                    |              |       |  |
|--------------------|--------------|-------|--|
| Comment:           | 713-209-2400 | Date: |  |
| Corrective Action: |              | Date: |  |

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | STORAGE OF SUPL  |       |            |
| Comment:           | Tank labeled as "out of service" stored in tank battery. |       |            |
| Corrective Action: | Comply with Rule 603.f .                                 | Date: | 12/02/2019 |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|      |      |        |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

| Type:                       | #   |       | corrective date |
|-----------------------------|-----|-------|-----------------|
| Bird Protectors             |     |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Horizontal Heated Separator | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Horizontal Heater Treater   | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |
| Gas Meter Run               | # 1 |       |                 |
| Comment:                    |     |       |                 |
| Corrective Action:          |     | Date: |                 |

| <b>Tanks and Berms:</b> |          |                     |                     |             |        |  |
|-------------------------|----------|---------------------|---------------------|-------------|--------|--|
| Contents                | #        | Capacity            | Type                | Tank ID     | SE GPS |  |
| PRODUCED WATER          | 1        | 400 BBLs            | STEEL AST           |             | ,      |  |
| Comment:                |          |                     |                     |             |        |  |
| Corrective Action:      |          |                     |                     |             | Date:  |  |
| <b>Paint</b>            |          |                     |                     |             |        |  |
| Condition               | Adequate |                     |                     |             |        |  |
| Other (Content)         |          |                     |                     |             |        |  |
| Other (Capacity)        |          |                     |                     |             |        |  |
| Other (Type)            |          |                     |                     |             |        |  |
| <b>Berms</b>            |          |                     |                     |             |        |  |
| Type                    | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |        |  |
| Metal                   | Adequate |                     |                     | Adequate    |        |  |
| Comment:                |          |                     |                     |             |        |  |
| Corrective Action:      |          |                     |                     |             | Date:  |  |
| <b>Venting:</b>         |          |                     |                     |             |        |  |
| Yes/No                  |          |                     |                     |             |        |  |
| Comment:                |          |                     |                     |             |        |  |
| Corrective Action:      |          |                     |                     |             | Date:  |  |
| <b>Flaring:</b>         |          |                     |                     |             |        |  |
| Type                    |          |                     |                     |             |        |  |
| Comment:                |          |                     |                     |             |        |  |
| Corrective Action:      |          |                     |                     |             | Date:  |  |

**Inspected Facilities**

Facility ID: 258684 Type: WELL API Number: 081-07003 Status: PR Insp. Status: PR

**Producing Well**

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402228978    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978469">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978469</a> |
| 689803231    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978460">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4978460</a> |