

Inspection Photos  
Operator: Kinder Morgan  
Location/API #: 033-06081  
Date: 10-29-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing within the interim reclamation areas, largely with a mixture of wheatgrasses and smooth brome, as well as rubber rabbitbrush shrubs.





Photo 3. View of musk thistles that appear to have been cut and removed as a treatment measure.





Photo 4. View of reference area vegetation northwest of the project area, comprised of grass field, dominated with smooth brome.