

Inspection Photos
Operator: Kinder Morgan
Location/API #: 033-06183
Date: 10-29-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the northern fill slope from the northeastern corner facing westward. Disturbed soils are tracked and hydromulched. Drainage swales are berms are placed around the well pad perimeter.



Photo 3. View of the tracking on slopes within the southeastern project area.



Photo 4. View of topsoil signage and stockpiling within the eastern project area.



Photo 5. View of reference area in background, comprised of a cultivated field that is not supporting crop at this time.