

Location						
Overall Good: <input checked="" type="checkbox"/>						
Signs/Marker:						
Type	TANK LABELS/PLACARDS					
Comment:	No NFPA placard, or contents of Concrete vault see pic 3					
Corrective Action:	Install sign to comply with Rule 210.d.				Date:	12/04/2019
Emergency Contact Number:						
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>
Overall Good: <input checked="" type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:	<input type="text"/>					
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
Type	WELLHEAD					
Comment:	Red AG fencing					
Corrective Action:					Date:	
Equipment:						
Type: Ancillary equipment	# 2				corrective date	
Comment:	Automation					
Corrective Action:					Date:	
Type: Bradenhead	# 1					
Comment:						
Corrective Action:					Date:	
Type: Plunger Lift	# 1					
Comment:						
Corrective Action:					Date:	
Type: Bird Protectors	# 1					
Comment:						
Corrective Action:					Date:	
Type: Horizontal Heated Separator	# 1					
Comment:						
Corrective Action:					Date:	
Tanks and Berms:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1		BV CONCRETE		,	
Comment:	No volume or nfpa placard					

Corrective Action:	Date:
--------------------	-------

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: Shares containment with oil tanks				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

Flaring:

Type	
Comment:	
Corrective Action:	
Date:	

Inspected Facilities

Facility ID: 427109 Type: WELL API Number: 123-34871 Status: SI Insp. Status: SI

Producing Well

Comment: [PR](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On 11-4-19 at approximately 1318 I, Inspector Justin Medina conducted an on-site inspection at KPK- API 123-34871 -Bosky PC Z22-14 in Weld County Colorado. While there, I observed producing well During this inspection the following possible compliance issues were observed: No content label on vault see pic 3,4 Install sign to comply with Rule 210.d.12/4/19</p> <p>Talked to pumper and pumper stated "this is how we got the well".</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	medinaj	11/04/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402230643	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980188
699500245	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4980177