

Inspection Photos
Operator: Catamount Energy
Location/API #: 007-06098
Date: 11-1-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southeastern fill-slope from the southwestern corner facing northeastward. Revegetation is progressing on fill slopes with perennial grasses such as western wheatgrass and smooth brome, as well as forbs such as Arizona gumweed.



Photo 3. View of rig cable debris within the southeastern project area.



Photo 4. View of erosional channel, approximately 2 to 3 feet wide and 2 feet deep, within the southeastern project area.



Photo 5. View of well pad cut-slope with poor revegetation. Rilling and scouring observed on bare soils.



Photo 6. View of reference area vegetation, comprised of mixed conifer woodland with grass and gambel oak-dominated understory.



Photos 7, 8. View of shells from firearms and sign with shot-holes observed within the project area.