

Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #1 – Facility sign.

Photo #2 – Overview of tank battery from northeast.



Inspection Photos
Location Name: Piceance 29-07 Pad
Location ID: #334436
Inspection Date: November 08, 2019



Photo #3 – Signs stored outside NE corner of tank battery were not installed on inspection date.

Photo #4 – View inside of tank battery containment area from NE. Note fluids inside of lined tank battery area.

Tank NFPA placards on east side of tanks read “Produced Water.”



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #5 – View of tank battery from SW corner.

Photo #6 – Overview of wellheads from NW corner.

Tank NFPA placards on west side of tanks read
“Condensate/Produced Water.”



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #7 – View of day tanks and chemical pumps located north of wellheads.



Photo #8 – View of oily waste accumulation beneath 29-17W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #9 - View of oily waste accumulation beneath 29-15W wellhead.



Photo #10 - View of oily waste accumulation beneath 29-13W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #11 - View of oily waste accumulation beneath 29-11W wellhead.



Photo #12 - View of oily waste accumulation beneath 29-09W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #13 -View of oily waste accumulation beneath 29-07W wellhead.



Photo #14 - View of oily waste accumulation beneath 29-06W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #15 - View of oily waste accumulation beneath 29-08W wellhead.



Photo #16 - View of oily waste accumulation beneath 29-10W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #17 - View of oily waste accumulation beneath 29-12W wellhead.



Photo #18 - View of oily waste accumulation beneath 29-04W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #19 - View of oily waste accumulation beneath 29-03W wellhead.



Photo #20 - View of oily waste accumulation beneath 29-01W wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #21 - View of oily waste accumulation beneath 29-01E wellhead.



Photo #22 - View of oily waste accumulation beneath 29-02E well sign.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #23 - View of oily waste accumulation beneath 29-04M wellhead.



Photo #24 - View of oily waste accumulation beneath 29-07M wellhead.



Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #25 – Overview of heated vertical separators from southeast.




Photo #26 – View of 29-09W separator and flowline riser from west side. Note scale buildup on flowline riser, beneath hammer union (circled).



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

Location Name: Piceance 29-07 Pad

Location ID: #334436

Inspection Date: November 08, 2019



Photo #27 – Close-up view of scale buildup beneath hammer union on flowline riser from previous photo.



Photo #28 – View of salt staining on gravel in vicinity of 29-09W separator.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources