

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06482**  
**Date: 11-1-2019**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing here with grasses such as western wheatgrass and shrubby rubber rabbitbrush.



Photo 3. View of area adjacent to the northern facilities where stormwater flows off of the well pad westward, and resulting in erosion within the northwestern project area.



Photo 4. View of erosional headcut in the northwestern project area facing upstream. Erosional channel is approximately 1 to 3 feet wide and deep.



Photo 5. View of erosional channeling within the northwestern project area, facing downslope.



Photo 6. View of reference area vegetation comprised of open gambel oak and mountain mahogany shrubland mosaic with open grass fields and pinyon/juniper stands.