

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

687905813

FIELD INSPECTION FORM
 Loc ID 311895 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Inspections, All		inspections@catamountep.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89106	WELL	PR	08/15/2007	GW	067-08210	A H TERRELL 1A	PR
282114	WELL	PR	06/19/2018	GW	067-09094	IGW 106	PR
436554	WELL	PR	01/24/2018	GW	067-09907	IGW 152	PR

General Comment:

Operator was given corrective actions in previous field inspection reports for other locations (doc#'s 687903685, 687903691, 687904515, 687904515, 687904846, 687905609) for non-compliance and inadequate maintenance of secondary containment. Current liner is inadequate as evident by numerous holes and tears. This is a follow-up inspection and it appears corrective actions have not been performed and are still required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Company contact information posted. Missing local emergency services number or "911" on all signs.

Corrective Action: Update sign information per Rule 210. Corrective action from previous inspection Doc# 687905609

Date: 10/02/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	400 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment poly tarp liner of IGW 152 & 106 has multiple tears and holes in liner base and on walls. Tires have been removed, liner is not adequate at time of inspection. Corrective action from previous inspection Doc# 687905609. CA date retained from previous inspection retained to document days of non-compliance.			
Corrective Action:	Use adequate material or engineering to make secondary containment sufficiently impervious in order to comply with Rules 605.a(4) and 906.d			Date: 10/02/2019

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 89106 Type: WELL API Number: 067-08210 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 282114 Type: WELL API Number: 067-09094 Status: PR Insp. Status: PR**Producing Well**Comment: Producing

Corrective Action:

Date:

Facility ID: 436554 Type: WELL API Number: 067-09907 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905814	AH Terrell Re-inspection Photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4985997