

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/11/2019

Submitted Date:

11/12/2019

Document Number:

687905815

FIELD INSPECTION FORMLoc ID 325144 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10464

Name of Operator: CATAMOUNT ENERGY PARTNERS LLC

Address: 1801 BROADWAY #1000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Ferrin, Jeremy		jeremy.ferrin@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		inspections@catamountep.co m	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214119	WELL	PR	07/18/2018	GW	067-05429	A H TERRELL 1	PR
438347	WELL	PR	12/05/2017	GW	067-09913	IGW 154	PR

General Comment:

Operator was given corrective actions in previous field inspection reports for other locations (doc#'s 687903685, 687903691, 687904515, 687904515, 687904846, 687905609, 687905610) for non-compliance and inadequate maintenance of secondary containment. Current liner is inadequate as evident by numerous holes and tears. This is a follow-up inspection and it appears corrective actions have not been performed and are still required.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	400 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

Paint

Condition	Adequate	<input type="text"/>
Other (Content)	<input type="text"/>	
Other (Capacity)	<input type="text"/>	
Other (Type)	<input type="text"/>	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Secondary containment poly tarp liner of IGW 154 has multiple tears and holes in liner base and on walls. Tires have been removed, liner is not adequate at time of inspection. Corrective action from previous inspection Doc# 687905609. CA date retained from previous inspection retained to document days of non-compliance			
Corrective Action:	Use adequate material or engineering to make secondary containment sufficiently impervious in order to comply with Rules 605.a(4) and 906.d			Date: 10/02/2019

Venting:

Yes/No	NO	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>	<input type="text"/>
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	
	Date:	<input type="text"/>

Inspected FacilitiesFacility ID: 214119 Type: WELL API Number: 067-05429 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Facility ID: 438347 Type: WELL API Number: 067-09913 Status: PR Insp. Status: PR**Producing Well**Comment: Producing.

Corrective Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905816	AH Terrell 1 Re-inspection.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4985998