

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate (X4)		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate (X2)		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	On East Tank Battery on the Southwest corner the Concrete and Fiberglass Condensate Vaults are missing the Capacity labels. See photo 4		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	12/13/2019

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Emission Control Device	# 10		
Comment:			
Corrective Action:		Date:	
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Glycol Unit		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electrical and Automation Equipment		
Corrective Action:		Date:	
Type: Bird Protectors	# 19		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 4		
Comment:			

Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	
Type: VRT	# 5		
Comment:			
Corrective Action:		Date:	
Type: Other	# 2		
Comment:	Pump Houses		
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Horizontal Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs			
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLs			40.383370,-104.221950
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	8	400 BBLs			40.383250,-104.221330
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	9	400 BBLs			
Comment:					
Corrective Action:					Date:
<u>Paint</u>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Comment:	Shares berm wtih Crude Oil Tanks	
Corrective Action:		Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>433694</u>	Type:	<u>WELL</u>	API Number:	<u>123-37750</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>433696</u>	Type:	<u>WELL</u>	API Number:	<u>123-37751</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>433710</u>	Type:	<u>WELL</u>	API Number:	<u>123-37755</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				
Facility ID:	<u>433712</u>	Type:	<u>WELL</u>	API Number:	<u>123-37756</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
<u>Producing Well</u>									
Comment:	<u>PR</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/07/2019 at approximately 13:50, I, Inspector Erica Petrie, conducted a Field Inspection at Highpoint Operating Corporation, Hawkins 5-61-21 Tank Battery, Location #433684 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: At East Tank Battery on the Southwest corner the Concrete and Fiberglass vaults are missing the Capacity labels, see photo 4. Comply with Rule 210.d. Corrective Action date 12.13.2019 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Educational Inspections</p>	petrie	11/12/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300841	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986060