

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/08/2019

Submitted Date:

11/12/2019

Document Number:

693801245**FIELD INSPECTION FORM**Loc ID 322448 Inspector Name: BROWNING, CHUCK On-Site Inspection ☐ 2A Doc Num:                     **Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
- 
- ☒
- FOLLOW UP INSPECTION REQUIRED
- 
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**8 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Ried, Jordan	970-563-4000	maralextechjr@gmail.com	<a href="#">All Inspections</a>
Browning, Chuck	970-433-4139	chuck.browning@state.co.us	<a href="#">Field Inspector</a>
Graves, Jim	970-858-8550	mrinc20@qwestoffice.net	<a href="#">Operations Manager</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210530	WELL	TA	02/01/2017	GW	045-06286	BEAR GULCH 26-2	TA

**General Comment:**COGCC staff performed a routine field inspection on 11/8/2019.  
Issues were found requiring corrective action. CA(s) from previous inspection not completed.

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:	BLM 265		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-858-8550 or 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	PIT		
Comment:	Hogwire & T-post		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Dehydrator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			

Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 210530 Type: WELL API Number: 045-06286 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last MIT 8/10/2015.

Well was found in state of Temporary Abandonment. TA status has not been approved via Form 4. Ongoing reporting via Form 7 has not been conducted

Corrective Action: Submit for Form 4 to request approval for TA status . Submit Form 7s and bring reporting up to date.

Date: 11/29/2019

## Reclamation - Storm Water - Pit

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PITType: BlowdownLined: NO

Pit ID:

Lat: 39.598931Long: -108.686848Reference Point: SEOther: Length: 16Width: 16**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment: Corrective Action: Date: 

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard:

Comment: Corrective Action: Date: Type: BlowdownLined: NO

Pit ID:

Lat: 39.598830Long: -108.687009Reference Point: SEOther: Length: 22Width: 18**Lining:**

Liner Type:

Liner Condition:

Comment: Corrective Action: Date: **Fencing:**Fencing Type: LivestockFencing Condition: AdequateComment: Corrective Action: Date: **Netting:**

Netting Type:

Netting Condition:

Comment:		Date:
Corrective Action		
Anchor Trench Present:	Oil Accumulation: <u>NO</u>	2+ feet Freeboard:
Comment:		Date:
Corrective Action		

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693801252	Inspection photos 11/8/2019	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986731">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4986731</a>