

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/06/2019

Submitted Date:

11/06/2019

Document Number:

687905792

FIELD INSPECTION FORM

Loc ID 313489 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 10 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Hannigan, Michael	(970) 882-5532	CO2Source_Regulatory@kindermorgan.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224222	WELL	PR	03/06/2018	GW	083-06287	SAND CANYON (DEEP) UNIT 2-36-18 6	PR

General Comment:

Site inspection and equipment inventory with photos at the end of this report.

Location			
Lease Road:			
Type	Access		
comment:	Gravel road access.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign posted at entrance to location has been damaged by bullet holes.		
Corrective Action:	Replace sign per Rule 210.	Date:	12/06/2019
Emergency Contact Number:			
Comment:	Company contact information is current. Missing local area emergency contact information or "911" on location sign. See photo.		
Corrective Action:	Update sign to include local emergency contact or "911" per Rule 210.	Date:	12/06/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Flow Line	# 1		corrective date
Comment:	1-6" SS flowline from wellhead to offsite gathering system.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224222 Type: WELL API Number: 083-06287 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing.](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Rip Rap	Pass					
Gradient Terraces	Pass	Ditches	Pass			
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Culverts	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for 1000Gal glycol tank.

Comment: Corrective Action: Date:
Pits: NO SURFACE INDICATION OF PIT
Attached Documents
 You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402232968	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982528
687905793	Damaged sign missing emergency contact information	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982498
687905794	Overview photo looking West.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982499