

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/24/2019

Submitted Date:

11/06/2019

Document Number:

688800656**FIELD INSPECTION FORM**
 Loc ID 334042 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 74650Name of Operator: RIM OPERATING INCAddress: 5 INVERNESS DRIVE EASTCity: ENGLEWOOD State: CO Zip: 80112**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Elledge, Randy	505-320-4969	relledge@rimop.com	SW Inspection Reports
Rector, Mike	720-221-1677	mhr@rimop.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Ortiz, Liz	303-799-9828 Ext. 304	lortiz@rimop.com	SW Inspection Reports
Heil, John		john.heil@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289620	WELL	PR	09/01/2019	GW	067-09333	PAYNE C-2	EI
289621	WELL	PR	03/01/2012	GW	067-09332	PAYNE C 1A	EI
299999	WELL	PR	06/22/2010	GW	067-09651	PAYNE 22	EI

General Comment:

On October 24, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Rim Operating Payne C #1A. For the most recent field inspection report of this facility, please refer to document #693900105.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	95 bbl. below grade tanks have free standing signs nearby.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Free standing signs near each well head.		
Corrective Action:			Date:
Type	BATTERY		
Comment:	ASTs are labeled with capacity, contents, and have NFPA placards.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Posted on location signs.		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Dismantled pump jack on Payne C #1A. Plunger lift currently in use.		
Corrective Action:	Comply with Rule 603.f.		Date: 02/06/2020
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
Lube Oil	Tank	<= 1 bbl	
Comment:	Stained soil at base of stock tank used as secondary containment for lube oil container.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: 12/06/2019
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Steel post and hog wire fencing.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Guard fencing present.		
Corrective Action:			Date:

Equipment:				corrective date
Type: Ancillary equipment	# 3			
Comment:	Telemetry equipment.			
Corrective Action:				Date:
Type: Prime Mover	# 1			
Comment:	Natural gas powered.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:
Type: Pump Jack	# 1			
Comment:	Dismantled during this inspection.			
Corrective Action:				Date:
Type: Gas Meter Run	# 3			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 7			
Comment:	Present on heated steel ASTs and separators.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	Open Top		37.013386,-107.521515	
Comment:	Below grade open top tank with expanded metal top and in walled pit with earthen berms.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	Open Top		37.013371,-107.522017

Comment:	Below grade open top tank with expanded metal top and in walled pit with earthen berms.		Date:	
Corrective Action:			Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	95 bbl.	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	300 BBLS	HEATED STEEL AST		37.013325,-107.521644
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	<u>289620</u>	Type:	<u>WELL</u>	API Number:	<u>067-09333</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>289621</u>	Type:	<u>WELL</u>	API Number:	<u>067-09332</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>299999</u>	Type:	<u>WELL</u>	API Number:	<u>067-09651</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail	Culverts	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass	Compaction	Pass	Material Handling And Spill Prevention	Pass	Secondary containment for lube oil container.

Comment: Wattles along eastern fill slope are damaged and not functioning.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 24, 2019 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Rim Operating Payne C #1A. For the most recent field inspection report of this facility, please refer to document #693900105. The pump jack at the Payne C #1A has been dismantled and is currently not in use. A plunger lift is in use on this well. Stained soil is present along the base of the stock tank being used as secondary containment for a lube oil container. Location BMPs are in disrepair and require attention.	hughesjo	11/06/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402232686	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982213
688800657	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4982203