

Inspection Photos
Operator: BP America
Location/API #: 067-08393
Date: 11-6-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Location is infested with weeds.



Photo 3. View of musk thistle infestation within the southwestern project area.



Photo 4. View of the beginning of Transect 1, within the project disturbance facing westward. Brown vegetation is dominated with weedy annual mustard. Scattered perennial grasses such as crested wheatgrass and intermediate wheatgrass are present, although poorly established.



Photo 5. Birdseye view of vegetation at the midpoint along the vegetation transect, largely comprised of weedy mustard (likely *Sisymbrium altissimum*) and Canada thistle.



Photo 6. View from the beginning of Transect 2, within the reference area, facing westward.



Photo 7. Birdseye view of vegetation along Transect 2, largely comprised of smooth brome.



Photo 8. View of reference area west of the well pad, comprised of open grass field.