

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/12/2019

Submitted Date:

11/13/2019

Document Number:

693501711

### FIELD INSPECTION FORM

Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection   
451044 \_\_\_\_\_ Silver, Randy \_\_\_\_\_ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10633  
Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC  
Address: 1801 CALIFORNIA STREET #2500  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Leonard, Mike		mike.leonard@state.co.us	
,		Cogcc.inspections@crestone pr.com	ALL INSPECTIONS
Gomez, Jason		jason.gomez@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
451033	WELL	DG	04/02/2019		123-44938	Regnier Farms 1C-19H- B268	DG

**General Comment:**

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	DRILLING/RECOMP		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:  Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Sound walls		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**

Facility ID: 451033 Type: WELL API Number: 123-44938 Status: DG Insp. Status: DG

**Well Stimulation**

Stimulation Company: Liberty Oilfield Services Stimulation Type: HYDRAULIC FRAC  
Other: \_\_\_\_\_

**Observation:**

Maximum Casing Recorded: 8929 PSI Tubing: \_\_\_\_\_  
Surface: \_\_\_\_\_ Intermediate: \_\_\_\_\_  
Production: \_\_\_\_\_ Instantaneous Shut-In Pressure (ISIP) \_\_\_\_\_  
Bradenhead Psi: 11 Frac Flow Back: Fluid: \_\_\_\_\_ Gas: \_\_\_\_\_

Comment: At time of inspection crew was performing routine fracing operations.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Tracking Pad	In Process	Covering Materials	Pass	

Comment: At time of inspection service company was maintaining tracking pad and sweeping county road with skidsteer.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**COGCC Comments**

Comment	User	Date
Inspection due to a noise and odor complaint. At time of inspection I did not observe any unusual odor or noise. I Randy Silver and Supervisor Jason Gomez set up sound study equipment 350ft to the west of location(see Photos). Jason Gomez spoke with and got permission to set up equipment from landowner. At time of set up wind speed was 0 current temp was 47Deg with clear skys. We did observe a plane flying by. At time of inspection I did observe emissions from pump equipment on location.	silverr	11/13/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693501712	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987139">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987139</a>