

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/12/2019

Submitted Date:

11/13/2019

Document Number:

679706050**FIELD INSPECTION FORM**Loc ID 314960 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 53255Name of Operator: MARALEX RESOURCES INCAddress: P O BOX 338City: IGNACIO State: CO Zip: 81137**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Reid, Jordan	970-563-4000	maralextechjr@gmail.com	All inspections
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Graves, Jim	970-712-0099	mrinc20@qwestoffice.net	Operations Manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229980	WELL	PR	09/07/1995	GW	103-07639	SOLDIER CANYON 26-1	PR

General Comment:[COGCC Inspection Report Summary.](#)

On 11-12-2019 at approximately 12:15, inspector Rick Moran, conducted a follow up inspection at Maralex Resources well Soldier Canyon 26-1 in Rio Blanco county of FIR document 679705168.

The following compliance issues are uncompleted:

- 1) Missing well head sign. Photo 1. Complete by 9-13-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679706050.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Missing well head sign.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	09/13/2019
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLs	Open Top		39.661010,-108.704740	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	90 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	229980	Type:	WELL	API Number:	103-07639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well.								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Type: Blowdown

Lined: NO

Pit ID:

Lat: 39.673180

Long: -108.699590

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Wildlife

Fencing Condition: Adequate

Comment:

Corrective Action

Date:

Netting:

Netting Type: Fence/Net Combo

Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation: NO

2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706051	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987237