

Inspection Photos
Operator: BP America
Location/API #: 067-07174
Date: 11-6-2019



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing here, largely with smooth brome.



Photo 3. View of the northeastern cut-slope. Stabilization measures are needed on bare and eroding soils here.



Photo 4. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.