

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/13/2019

Submitted Date:

11/13/2019

Document Number:

694900769

FIELD INSPECTION FORM

Loc ID 311663	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input checked="" type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				Findings: 24 Number of Comments 0 Number of Corrective Actions <input type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287101	WELL	PR	07/31/2008	GW	045-12867	FEDERAL RMV 142-9	PR
287102	WELL	PR	10/27/2008	GW	045-12866	FEDERAL RWF 423-9	PR
287103	WELL	PR	10/24/2008	GW	045-12865	FEDERAL RWF 523-9	PR
287104	WELL	PR	07/30/2008	GW	045-12864	FEDERAL RWF 324-9	PR
287105	WELL	PR	10/14/2013	GW	045-12863	FEDERAL RWF 424-9	PR
287106	WELL	PR	10/22/2008	GW	045-12862	FEDERAL RWF 323-9	PR
287107	WELL	PR	09/10/2012	GW	045-12861	FEDERAL RWF 334-9	PR
287108	WELL	PR	06/14/2007	GW	045-12860	FEDERAL RWF 434-9	PR
287109	WELL	PR	10/27/2008	GW	045-12859	FEDERAL RWF 33-9	PR
287110	WELL	PR	07/31/2008	GW	045-12858	FEDERAL RWF 433-9	PR
287111	WELL	PR	06/05/2008	GW	045-12857	FEDERAL RWF 333-9	PR
287112	WELL	PR	07/11/2008	GW	045-12856	FEDERAL RWF 34-9	PR
287113	WELL	PR	07/31/2008	GW	045-12855	FEDERAL RWF 534-9	PR

General Comment: COGCC Inspection Report Summary On Wednesday 11/13/19 at approximately 1:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF 324-9, at Location # 311663 in Garfield County, Colorado. While there, I Noticed a stainless line from chemical pump going to well #RWF 423-9 was leaking at well head connection. I talked to Mike Gardner with Terra and said that he would send out a pumper immediately. Pumper arrived and fixed connection also removed all stained soil. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	have to cross small creek		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Noticed stainless line from chemical pump going to well #RWF 423-9 was leaking at well head connection. I talked to Mike Gardner with Terra and said that he would send out a pumper immediately. Pumper arrived and fixed connection also removed all stained soil.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	hog panel		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	hog panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 13		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			

Corrective Action:		Date:	
Type: Plunger Lift	# 13		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	STEEL AST		,
Comment:	80 bbl tank				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO	
Comment:		

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	287101	Type:	WELL	API Number:	045-12867	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287102	Type:	WELL	API Number:	045-12866	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287103	Type:	WELL	API Number:	045-12865	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287104	Type:	WELL	API Number:	045-12864	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287105	Type:	WELL	API Number:	045-12863	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287106	Type:	WELL	API Number:	045-12862	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287107	Type:	WELL	API Number:	045-12861	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	287108	Type:	WELL	API Number:	045-12860	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	287109	Type:	WELL	API Number:	045-12859	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	287110	Type:	WELL	API Number:	045-12858	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	287111	Type:	WELL	API Number:	045-12857	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	287112	Type:	WELL	API Number:	045-12856	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	287113	Type:	WELL	API Number:	045-12855	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Gravel						
Compaction		Gravel				
Berms		Ditches				have to cross a small creek

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Pumpers were immediate to respond when I called.	ramseys	11/13/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900775	694900769	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987943