

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/13/2019

Submitted Date:

11/13/2019

Document Number:

694900770

FIELD INSPECTION FORM

 Loc ID 335742 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|--------------|------------------------------------|---------|
| , TEP | 970-285-9377 | COGCCInspectionReports@terraep.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 275254 | WELL | PR | 07/27/2005 | OW | 045-13503 | CLOUGH RWF 321-16 | PR |
| 275255 | WELL | PR | 05/27/2005 | GW | 045-13504 | CLOUGH RWF 421-16 | PR |
| 275256 | WELL | PR | 07/06/2005 | OW | 045-13505 | CLOUGH RWF 521-16 | PR |

General Comment:

[COGCC Inspection Report Summary](#)

On Wednesday 11/13/19 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 8-16, at Location # 335742 in Garfield County, Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | | Date: |

Overall Good:

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | 911 |
| Corrective Action: | |
| | Date: _____ |

| | | | |
|---------------------------|--------|--|-------|
| Good Housekeeping: | | | |
| Type | DEBRIS | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

Multiple Spills and Releases?

| | | | |
|--------------------|--------------|--|-------|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | hog panel | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | hog panel | | |
| Corrective Action: | | | Date: |
| Type | TANK BATTERY | | |
| Comment: | hog panel | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Bird Protectors | # 2 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| Tanks and Berms: | | | | | |
|-------------------------|----------|---------------------|---------------------|-------------|--------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | <100 BBLs | STEEL AST | | |
| Comment: 80 bbl tank | | | | | |
| Corrective Action: | | | | | Date: |
| Paint | | | | | |
| Condition | Adequate | | | | |
| Other (Content) | | | | | |
| Other (Capacity) | | | | | |
| Other (Type) | | | | | |
| Berms | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Venting: | | | | | |
| Yes/No | NO | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |
| Flaring: | | | | | |
| Type | | | | | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Inspected Facilities

Facility ID: 275254 Type: WELL API Number: 045-13503 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 275255 Type: WELL API Number: 045-13504 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID: 275256 Type: WELL API Number: 045-13505 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Ditches | | | | |
| Compaction | | Culverts | | | | |
| | | Gravel | | | | |
| Berms | | Compaction | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 694900776 | 694900770 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4987944 |