

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-09904
Date: 11-6-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing here, largely with western wheatgrass and smooth brome.



Photo 3. View of erosional channel approximately 1 foot wide and deep, forming within the southwestern project area.



Photo 4. View of reference area west of the well pad, comprised of ponderosa pine forest with gambel oak understory.