

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/06/2019

Submitted Date:

11/07/2019

Document Number:

679705976

FIELD INSPECTION FORM

Loc ID 414369	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 96850 Name of Operator: TEP ROCKY MOUNTAIN LLC Address: PO BOX 370 City: PARACHUTE State: CO Zip: 81635				Findings: 14 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
414353	WELL	PR	07/12/2012	GW	103-11613	FEDERAL RGU 13-24-198	PR
414358	WELL	PR	07/09/2018	OG	103-11614	FEDERAL RGU 24-24-198	PR
414360	WELL	PR	09/01/2018	GW	103-11615	FEDERAL RGU 423-24-198	PR
414374	WELL	PR	10/22/2012	GW	103-11616	FEDERAL RGU 413-24-198	PR
414375	WELL	PR	12/15/2010	GW	103-11617	FEDERAL RGU 422-24-198	PR
414377	WELL	PR	07/12/2012	GW	103-11618	FEDERAL RGU 412-24-198	PR
414379	WELL	PR	08/04/2011	GW	103-11619	FEDERAL RGU 23-24-198	PR
414382	WELL	PR	10/18/2012	GW	103-11620	FEDERAL RGU 14-24-198	PR

General Comment:

COGCC Inspection Report Summary.

On 11-6-2019 at approximately 14:10, inspector Rick Moran, conducted a routine inspection at TEP well pad RGU 13-24-198 in Rio Blanco county.

The following compliance issues were observed:

1) Two fallen deadman markers. Photo 5. Complete by 11-27-2019.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report 679705976.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		

Comment:		Two fallen deadman markers.			
Corrective Action:		Install proper guy line markers per Rule 1003.a		Date: 11/27/2019	
Type: Horizontal Heated Separator		# 4			
Comment:					
Corrective Action:				Date:	
Type: Other		# 1			
Comment:		Equipment building.			
Corrective Action:				Date:	
Type: Gas Meter Run		# 1			
Comment:					
Corrective Action:				Date:	
Type: Pig Station		# 1			
Comment:					
Corrective Action:				Date:	
Type: Plunger Lift		# 9			
Comment:					
Corrective Action:				Date:	
Type: Ancillary equipment		# 3			
Comment:		One container of SCI-8760, 1 container of MC FA-4933, and 1 container of methanol all with secondary containment.			
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	500 BBLS	STEEL AST		39.945730,-108.347200
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent		Adequate	
Comment:					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLS	STEEL AST		39.945730,-108.347200
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent		Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	414353	Type:	WELL	API Number:	103-11613	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414358	Type:	WELL	API Number:	103-11614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414360	Type:	WELL	API Number:	103-11615	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414374	Type:	WELL	API Number:	103-11616	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414375	Type:	WELL	API Number:	103-11617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414377	Type:	WELL	API Number:	103-11618	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414379	Type:	WELL	API Number:	103-11619	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			
Facility ID:	414382	Type:	WELL	API Number:	103-11620	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well on plunger lift.								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass			Material Handling And Spill Prevention	Pass	

Comment: No apparent significant soil migration, erosion, or soil movement on location.

Corrective Action: Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402234096	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983572
679705977	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983561