

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/07/2019

Submitted Date:

11/07/2019

Document Number:

699300520

FIELD INSPECTION FORM
 Loc ID 318147 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Pesika, Conor		conor.pesicka@state.co.us	
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240710	WELL	PR	10/01/2018	OW	123-08498	JACK MLEYNEK 1	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign faded and emergency number is not legible		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	12/07/2019

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Dead weeds all around PU,WH and Electric panel,transformers and meter box		
Corrective Action:	Comply with Rule 603.f	Date:	11/14/2019

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	Fabricated angle iron in disrepair		
Corrective Action:	Comply with Rule 604.c.(2)M	Date:	11/22/2019

Equipment:			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Electric panel, transformers and meter box		
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 240710 Type: WELL API Number: 123-08498 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/7/19 at approximately 0930 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at KP Kauffman:</p> <p style="text-align: right;">Jack A. Mleynek #1 at API #05-123-08498 in Weld County Colorado.</p> <p>While there, I observed a producing wellsite. During this inspection the following possible compliance issues were observed: Rule 603.f Housekeeping: Dead weeds/debris around WH, PU and Electric panel, transformers and meter box. CA date 11/14/2019 see photos # 3, 4, 5, 6 and 7. Rule 604.c.(2)M Housekeeping: Angle iron fence around PU is missing a pole and is in disrepair. CA date 11/22/2019 see photos #6 and 7. Rule 210.e Signs: WH sign is faded and emergency number is not legible and needs to be replaced. CA date 12/7/2019 see photos #1 and 2. Location is wet, weather is overcast/cloudy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	11/07/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402234272	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983759
699300521	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983748