



Location			
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	Mechanical issue, electrical motor missing and belts laying on ground		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 09/21/2019
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Hog fence		
Corrective Action:			Date:
<b>Equipment:</b>			
			corrective date
Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:			Date:
<b>Venting:</b>			
Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 241787 Type: WELL API Number: 123-09576 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary</b>                      On Thursday 11/6/2019 at approximately 1200 hrs, I, Inspector Robbie Revas, conducted an on-site inspection at a KP Kauffman site Rocky Mountain Fuel Co #1, at API #05-123-09576 in Weld County Colorado.                      While there, I observed a SI well site. This is a follow up inspection per Doc. #693501153 During this inspection the following possible compliance issue appears to have been addressed:                      Weeds: Rule 603.f weeds have been cut and removed from location. See photos 1, 2 &amp; 3. During this inspection the following possible compliance issue were observed and is now delinquent per above Doc.:                      Mechanical Issue: Rule 605 d unit electrical motor has been removed and belts laying on ground. Corrective action date 9/21/19 see photos 4 &amp; 5.                      Weather conditions: Cloudy and location dry                      A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.                      This is a summary of inspection report.</p>	revasr	11/07/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402234275	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983762">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983762</a>
699300531	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983753">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4983753</a>