

Inspection Photos

API: 05-055-06309

Operator: ALTA MESA SERVICES

Inspection Date: 11/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 1. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 2. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 3. Facing west along the cut slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 4. Facing northeast toward the location. Reclamation was performed at the west side of the location (left side of photo) and the east side of the location (right side of photo) was not reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 5. Facing north toward the area that was reclaimed. Reclamation was not successful. There are weed and cover crop debris throughout the area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 6. View of ground cover shows cover crop and weed debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 7. Northwest side of the location facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 8. View of ground cover shows cover crop and weed debris.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 9. Facing southwest at the reclaimed portion of the location (right) and area not reclaimed (upper left). There are numerous undesirable weeds growing throughout the area. (Russian thistle, Pigweed). There are numerous dead trees that remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 10. Facing southwest toward the area that was not reclaimed. Gravel remains in this area. The fill slope is shown in the left side of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 11. Southwest of the location where unpermitted disturbance occurred. Facing northeast. Vegetation is established throughout this area. The predominate species observed is Crested wheatgrass which is not present in the surrounding reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019

Inspection Photos



Photo 12. Facing west toward the surrounding undisturbed reference area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06309 | Date: 11/6/2019