

Inspected Facilities

Facility ID: 461838 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Complaint

Comment: Inspection in response to complaint. 18#200447965

Field Inspector Assigned: Erica Petrie

Complaint Received:

Date: 8/19/2019

Complaint Contacted:

Date: 8/20/2019 @

Location #: 461838

Inspection Document #: 696300502

Nature of complaint: Odor

Field Inspector Actions:

On 8/19/2019, I received a complaint in regards to odor suspected to be coming from the Colorado River Pad, owned and operated by EnerPlus Resources (USA) Corporation.

On 8/20/2019, I performed an inspection of the Colorado Rivers Pad, while on inspection I noted that both wells on the location are hard shut in at the wellhead. Contractors are in the beginning stages of assembling flowback operations, no chemicals or fluids were observed to be on, nor stored at the location.

I utilized CDPHE Reg. 2 detection method at 40.62312, -104.90365, with no detection of odor. Wind was observed to be at 2mph out of the northwest.

Additionally, I performed an inspection of the Colorado Lakes Pad, Location ID 449968, the two wells and production facility were observed to be on and producing at time of inspection. I utilized Reg. 2. Detection method at 40.62696, -104.90531, with no detection of odor.

No violation of COGCC rules were observed at the time of the inspection.

All information reviewed and site inspection information were submitted to the complaint specialist for further review.

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696300503	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4915112