

Inspection Photos

API: 05-055-06017

Operator: OXY USA INC

Inspection Date: 11/6/2019



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 1. The disturbance along the side of the access road has been seeded and hydro-mulched.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 2. The culvert outlet protection has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 3. Erosion channel has been repaired at the culvert outlet. Rock rip/rap, wattles, and erosion matting was placed in channel. Larger rip rap was installed.

Lat/Long:37.69829,-105.21889



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 4. Facing south. This area along the side of the road has a deep erosion channel and BMP's have not been repaired. Lat/Long:37.69860,-105.21673



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 5. Facing north. This area along the side of the road has a deep erosion channel and BMP's have not been repaired. Rock check dams have been displaced. As stated in the previous inspection "Stormwater will flow toward the side and will erode the into road."
Lat/Long:37.69860,-105.21673



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 6. Erosion channel has been repaired at the culvert outlet. Rock rip/rap and erosion matting was placed in channel. Lat/Long:37.70004,-105.21143



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 7. The disturbance along the side of the access road has been seeded and hydro-mulched. Inlet protection is installed at the culvert.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019

Inspection Photos



Photo 8. Facing south toward the location. It appears noxious weeds were removed and controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-055-06017 | Date: 11/6/2019