

# Inspection Photos

API: 05-055-06064

Operator: OXY USA INC

Inspection Date: 11/6/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-055-06064 | Date: 11/6/2019

## Inspection Photos



**Photo 1.** There is erosion occurring along the access road to the location. Stormwater is directed off the road at the point creating an erosion channel. Lat/Long:37.70081,-105.20980.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06064 | Date: 11/6/2019



## Inspection Photos



**Photo 2.** It appears noxious weeds have been removed and controlled for the season.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-055-06064 | Date: 11/6/2019