

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

11/14/2019

Submitted Date:

11/14/2019

Document Number:

699500304

**FIELD INSPECTION FORM**
 Loc ID 434206 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

4 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434203	WELL	SI	10/01/2018	OW	123-38019	PETTINGER 30C-18HZ	SI
434204	WELL	SI	07/01/2018	OW	123-38020	PETTINGER 4C-18HZ	SI
434205	WELL	AB	08/01/2014	OW	123-38021	PETTINGER 4NE-18HZX	AB
434207	WELL	SI	10/01/2018	OW	123-38022	PETTINGER 30N-18HZ	SI
434208	WELL	SI	10/01/2018	OW	123-38023	PETTINGER 3N-18HZ	SI
437694	SPILL OR RELEASE	CL	06/20/2014		-	SPILL/RELEASE POINT	CL

**General Comment:**

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Ancillary equipment

# 10

Comment: Automation

Corrective Action:

Date:

Type: Bradenhead

# 5

Comment:

Corrective Action:

Date:

Type: Plunger Lift

# 5

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 434203	Type: WELL	API Number: 123-38019	Status: SI	Insp. Status: SI
Facility ID: 434204	Type: WELL	API Number: 123-38020	Status: SI	Insp. Status: SI
Facility ID: 434205	Type: WELL	API Number: 123-38021	Status: AB	Insp. Status: AB
Facility ID: 434207	Type: WELL	API Number: 123-38022	Status: SI	Insp. Status: SI
Facility ID: 434208	Type: WELL	API Number: 123-38023	Status: SI	Insp. Status: SI
Facility ID: 437694	Type: SPILL OR	API Number: -	Status: CL	Insp. Status: CL

**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: Corrective Action:  Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of soil may have been distorted due to weather conditions.	medinaj	11/14/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500305	pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989008">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989008</a>