

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



Production facility



Wellhead

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



West crude oil tank leaks and stained soil



East crude oil tank leak

Inspection Photos
Location Name: State Anderson 1-36
Location ID: 307182



Crude oil tank berm