

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/14/2019

Document Number:

694900779

**FIELD INSPECTION FORM**

Loc ID 335453 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261878	WELL	PR	04/17/2002	GW	045-07992	LANGSTAFF RMV 141-16	PR
261880	WELL	PR	04/18/2002	GW	045-07994	LANGSTAFF RWF 313-16	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday 11/14/19 at approximately 11:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RWF313-16, at Location # 335453 in Garfield County, Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

**Location****Lease Road:**

Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	911	Date:	
Corrective Action:			

**Good Housekeeping:**

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	hog panel		
Corrective Action:		Date:	

**Equipment:**

Type: Plunger Lift	# 2		corrective date
Comment:			
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 261878 Type: WELL API Number: 045-07992 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 261880 Type: WELL API Number: 045-07994 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction		Compaction				
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694900785	694900779	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989249">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989249</a>