

Location			
Lease Road:			
Type	Access		
comment:	Dead weeds all along access road		
Corrective Action:	Comply with Rule 603.f	Date:	11/21/2019
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	No capacity sign on oil tank.		
Corrective Action:	Comply with rule 210.b	Date:	06/06/2019
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	DEBRIS		
Comment:	Remove weeds around sep, tnk btry, and wh. Remove trash and unused oil containers inside pumping unit house. stained soil in various areas on location. buckets and yellow lid around location.		
Corrective Action:	Comply with Rule 603.f	Date:	10/16/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	WELLHEAD		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbwire		

Corrective Action:		Date:	
Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Does not appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas engine		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1		STEEL AST		,
Comment:	No capacity sign on oil tank. Thief hatch appears to be open to atmosphere.				
Corrective Action:	Comply with Rule 210.b				Date: 06/16/2019

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbl	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares containment with crude oil tanks				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240554 Type: WELL API Number: 123-08342 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 11/14/19 at approximately 1445hrs. I, Inspector Robbie Revas conducted an onsite inspection at Cuykendall 12 Smith Energy Corp 123-08342 in Weld County Colorado. While there, I observed Shut in well This is a follow up inspection from document # 688400338 and 685100948. Corrective Actions from previous inspection appear to be delinquent. During this inspection the following possible compliance issues were observed: 603.f Housekeeping: Dead weeds around sep, trk btry, and wh. Trash and unused oil containers inside pumping unit house. stained soil in various areas on location. buckets and yellow lid around location. see photos 1, 3, 4, 7, 8, 11, 12 & 13. CA date 10/16/18 Rule 605.d: stained soil in motor house and around WH, possible leak in Separator house see photos 6 & 9. CA date 6/16/19 Rule 210.b: No capacity sign on oil tank. Thief hatch appears to be open to atmosphere. See photo 15 CA date 6/16/19 Submitting this inspection to enforcement due to compliance issues not being addressed. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report. Continuing Education Inspection</p>	revasr	11/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300577	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989323