

Inspection Photos
Location Name: SHINING 33-22
API#: 05-071-09398
INSP. #: 695101745



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN

Inspection Photos
Location Name: SHINING 33-22
API#: 05-071-09398
INSP. #: 695101745



PHOTO 3: AREA OF IMPACTED SOIL NEAR PRIME MOVER (ENGINE SKID). Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-14-19.



PHOTO 4: AREA OF IMPACTED SOIL AROUND WELLHEAD. Remove and dispose impacted material in approved manner, service and maintain equipment and self inspect to prevent recurrence of conditions per 1002.f(2) and 907. CA DATE 12-14-19.