

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type	Area	Volume		corrective date
Type: Bradenhead	# 2			
Comment:	BOTH ARE PLUMBED TO SURFACE			
Corrective Action:				Date:
Type: Ancillary equipment	# 2			
Comment:	TELEMETRY EQUIPMENT			
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 285478 Type: WELL API Number: 071-08834 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

Facility ID: 285482 Type: WELL API Number: 071-08835 Status: PR Insp. Status: PR

Producing Well

Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
THIS IS A FOLLOWUP INSPECTION TO INSPECTION DOC#687900622, CORRECTIVE ACTION HAS BEEN ADDRESSED.	beardsit	11/14/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695101739	INSPECTION PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989470