

# Inspection Photos

API: 05-071-06339

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/8/2019



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 05-071-06339 | Date: 11/8/2019

## Inspection Photos



**Photo 1.** Stormwater is not properly diverted off the road at this point. This issues is causing vehicle ruts and road damage.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06339 | Date: 11/8/2019



## Inspection Photos



**Photo 2.** The water leak at the wellhead has not been repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06339 | Date: 11/8/2019