

Inspection Photos

API: 05-071-06130

Operator: TIMBER CREEK OPERATING LLC

Inspection Date: 11/8/2019



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019

Inspection Photos



Photo 1. There are vehicle ruts and road damage along the main road to the location. This area is very slick and is a safety issue. The road requires gravel in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019

Inspection Photos



Photo 2. There are vehicle ruts and road damage along the main road to the location. This area is very slick and is a safety issue. The road requires gravel in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019

Inspection Photos



Photo 3. Sediment is beginning to accumulate in the culvert outlet at the stream crossing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019

Inspection Photos



Photo 4. The oil on the engine skid has been cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019

Inspection Photos



Photo 5. There is an area of oil stain soil near the engine skid that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-06130 | Date: 11/8/2019