

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

11/14/2019

Submitted Date:

11/15/2019

Document Number:

679706095

**FIELD INSPECTION FORM**

Loc ID 314745 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10539  
Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORP  
Address: 1125 ESCALANTE DR  
City: RANGELY State: CO Zip: 81648

**Findings:**

5 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Utah Gas Corp	720-425-0303	inspections@utahgascorp.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229469	WELL	PR	07/20/1968	GW	103-07125	DRAGON TRAIL UNIT	PR

**General Comment:**

[COGCC Inspection Report Summary.](#)

On 11-14-2019 at approximately 13:20, inspector Rick Moran, conducted a routine well inspection at Utah Gas well Dragon Trail Unit 1023 in Rio Blanco county.

No corrective actions were identified.

This is a summary of inspection report [679706095](#).

**Location**

Overall Good:

**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Gas Meter Run	# 1			
Comment:				
Corrective Action:		Date:		
Deadman # & Marked	# 2			
Comment:				
Corrective Action:		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLS	Open Top		39.858170,-108.770450
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	20 bbl
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 229469 Type: WELL API Number: 103-07125 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing well.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679706096	inspection photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989743">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989743</a>