

# Inspection Photos

API: 05-071-06218

Operator: MERIDIAN OIL INC

Inspection Date: 11/8/2019



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019

## Inspection Photos



**Photo 1.** Facing southwest toward the location which has been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019



## Inspection Photos



**Photo 2.** Facing southeast toward the location which has been recontoured and reclaimed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019



## Inspection Photos



**Photo 3.** Erosion controls are installed along the slope.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019



## Inspection Photos



**Photo 4.** Stormwater has begun to degrade the berm. Stormwater should be diverted toward the rock rip rap structure and berm needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019



## Inspection Photos



**Photo 5.** Facing northeast along the slope of the reclaimed location. This slope may need additional BMP's (Wattles) to slow the stormwater runoff.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-071-06218 | Date: 11/8/2019