

Inspection Photos
Location Name: Cleveland #8
Location ID: 332926



Photo1 Well head and PU



Photo 2 Emergency contact number does not reflect current operator.

Inspection Photos
Location Name: Cleveland #8
Location ID: 332926




Photo 3 stained soil around well head and mechanical issue; 2" hammer union appears to be leaking



Photo 4 Stained soil under PU motor. Mechanical issue: PU motor appears to be leaking.

Inspection Photos
Location Name: Cleveland #8
Location ID: 332926



Photo 5 Mechanical issue: PU motor belt appears to be in pieces and laying on ground. PU is not operable.