

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/14/2019

Submitted Date:

11/15/2019

Document Number:

696101554**FIELD INSPECTION FORM**Loc ID 309841 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10071Name of Operator: HIGHPOINT OPERATING CORPORATIONAddress: 555 17TH ST STE 3700City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--|---------------------------------|
| James, Brian | | bjames@hpres.com | All Inspections |
| Brown, Tim | | tbrown@hpres.com | MIT |
| , | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 314 | WELL | TA | 10/31/2019 | GW | 123-25446 | PETERSON 30-32 | TA |

General Comment:

This is WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Active.

Centralized Battery serves 6 Location IDs (430376, 309818, 309819, 309820, 309841, 410006).

(Well(s): 1: Producing | PR ; 9: Temporarily Abandoned | TA ; 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696101546 and/or Location ID #430376
for Battery / Facility, Equipment info.

| Location | | | |
|--|---|--------|----------------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Adequate | | |
| Corrective Action | L | | Date: |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Invalid company name posted at wellsite. Refer to Rule 210.b. See photo #1. | | |
| Corrective Action: | Post valid company name at wellsite. Comply w/ Rule 210.b. See photo #1. | | Date: 01/14/2020 |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Weed encroachment at wellsite. Refer to Rule 603.f. See photo #1. | | |
| Corrective Action: | Remove, manage, & control weeds at wellsite. Comply with Rule 603.f. See photo #1. | | Date: 11/22/2019 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | | | |
| Comment: | Refer to Field Inspection Report doc. #696101546 and/or Location ID #430376 for Battery / Facility, Equipment info. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Iron panel. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: | # | | corrective date |
| Comment: | Refer to Field Inspection Report doc. #696101546 and/or Location ID #430376 for Battery / Facility, Equipment info. | | |
| Corrective Action: | | | Date: |

| | | |
|--------------------|-----------------------------|-------|
| Type: Bradenhead | # 1 | |
| Comment: | Appears plumbed to surface. | |
| Corrective Action: | | Date: |
| Type: Plunger Lift | # 1 | |
| Comment: | | |
| Corrective Action: | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|---------------------|---------|-----------------------|
| | | | CENTRALIZED BATTERY | | 40.373587,-104.476895 |
| Comment: | Centralized Battery serves 6 Location IDs (430376, 309818, 309819, 309820, 309841, 410006). Refer to Field Inspection Report doc. #696101546 and/or Location ID #430376 for Battery / Facility, Equipment info. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 314 Type: WELL API Number: 123-25446 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Temporarily Abandoned | TA.

Form 5A doc. #401408571 indicates TA date: 06/09/2017. Approved.

Form 42 MIT-Notice doc. #402186795, Approved.

Form 21 doc. #402222065 indicates MIT done: 10/04/2019. Approval Pending.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | | | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary:</p> <p>On THU 11/14/2019 at approximately 11:49 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: PETERSON-65N63W /30SWNE Location ID: 309841 Well Name: Peterson 30-32 API: 05-123-25446 Location County: Weld County, Colorado Weather: Clear & Dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Active.</p> <p>Refer to Field Inspection Report doc. #696101546 and/or Location ID #430376 for Battery / Facility, Equipment info.</p> <p>During this inspection the following possible compliance issues were observed: 1.) Invalid company name posted at wellsite. Refer to Rule 210.b. Post valid company name at wellsite. Comply w/ Rule 210.b. Corrective Action date: 01/14/2020. See photo #1.</p> <p>2.) Weed encroachment at wellsite. Refer to Rule 603.f. Remove, manage, & control weeds at wellsite. Comply with Rule 603.f. Corrective Action date: 11/22/2019. See photo #1.</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of the inspection report.</p> | evinsb | 11/15/2019 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 696101555 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4989910 |